



Drilling and mounting of shafts and brass-etched adjustment wheels


Step 1:




Step 2:




Step 3:




Step 4:




Step 5:




Step 6:



Step 7:



Step 8:



Step 9:

